

Document Number 06-186


CORNER RECORD

Assessor Parcel Number 906-730-010, 013,

City of Murrieta

County of Riverside 034 & 037, California

Brief Legal Description Lots 10, 13, 34 & 37 of Tract Map 28148, M.B. 356/48-52



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Missing property corners were reestablished by locating monuments set per Tract Map 28148 and retracing record data as shown on Page 2 of 2.


A description of the physical condition of the monument as found and as set or reset: Set 1" iron pipe or lead and tack w/tag stamped "LS 6168". See Page 2 of 2 for details.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Oct 10 2006.

Signed D. Holmes L.S. or R.C.E. Number LS 6168

Expiration Date 3/31/06



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 2-14 2006 and examined

and filed 4-4 2006.

Signed Brian H. Hess For the County Surveyor



County Surveyor's Comment _____

**THE FILING OF THIS CORNER RECORD
 DOES NOT RELIEVE THE SURVEYOR
 FROM ANY RESPONSIBILITY OF THE
 FILING OF A RECORD OF SURVEY**

06-0047

SURVEYOR'S NOTES

- INDICATES FOUND 1" IRON PIPE W/TAG STAMPED "L.S. 5567" PER TR 28148, M.B. 356/48-52 (UNLESS OTHERWISE NOTED)
- ⊙ INDICATES SET LEAD AND TACK W/TAG STAMPED "L.S. 6168" IN TOP OF CURB ON THE PROLONGATION OF THE LOT SIDELINES, IN LIEU OF TAG STAMPED "L.S. 5567" PER TR 28148 M.B. 356/48-52
- () INDICATES MEASURED AND RECORD DATA PER TR 28148, M.B. 356/48-52

